Exova Warringtonfire Aus Pty Ltd Suite 2002a, Level 20 44 Market Street Sydney, New South Wales 2000 Australia T: +61 (0)2 8270 7600 F: +61 (0)2 9299 6076 W: www.exova.com

Postal Address: Suite 2002a, Level 20 44 Market Street Sydney, New South Wales 2000 Australia

Testing. Advising. Assuring.



EWFA CERTIFICATE OF ASSESSMENT		CERTIFICATE No : SFC 35233700		Page 1 of 3
Report Sponsor	Ce	tificate Issue Date	Proc	luct Name
Hilti (Aust.) Pty Ltd 1G Homebush Bay Drive, Rhodes, NSW 2138 Australia		14/04/2015		75/2.5" N firestop collars

Referenced Assessment Report	Test Method	Report Issue Date	Report Validity Date
EWFA 35233700	AS1530.4-2005	10/04/2015	30/04/2020

Introduction

The element of construction described below was assessed by this laboratory on behalf of the report sponsor in accordance with the stated test standard and achieved the results stated below. Refer to the referenced assessment report(s) or Regulatory Information Report(s) for a complete description of the assessed construction.

Description of Assessed Product and Performance

The scope of the assessment includes the fire resistance performance of a 150mm thick concrete floor penetrated by plastic pipes protected by Hilti CP 680 75/2.5" N firestop collars if tested in accordance with AS1530.4-2005 and assessed in accordance with AS 4072.1-2005.

Refer to the referenced assessment reports for a complete description of the assessed construction.

Conditions/Validity

- THIS CERTIFICATE IS PROVIDED FOR GENERAL INFORMATION ONLY AND DOES NOT COMPLY WITH THE REGULATORY REQUIREMENTS FOR EVIDENCE OF COMPLIANCE.
- Reference should be made to the relevant test report or regulatory information report to determine the applicability of the test result to a proposed installation. Full details of the constructions and justification for the conclusions given, along with the validity statements, are given in the assessment reports.
- The results of these fire tests may be used to assess fire hazard, but it should be recognized that a single test method will not provide a full assessment of fire hazard under all conditions.

TESTING AUTHORITY	Exova Warringtonfire Aus Pty Ltd	
Address	Suite 2002a, Level 20, 44 Market Str	reet, Sydney NSW 2000, Australia
Phone / Fax	+61 (0)2 8270 7600 / +61 (0)2 9299	6076
ABN	81 050 241 524	
Email / Home Page	www.exova.com	
Authorisation	Prepared By:	Reviewed By:
	Dhichelson D. Nicholson	K. Nicholls

© Exova Warringtonfire Aus Pty Ltd 2015



EWFA CERTIFICATE OF ASSESSMENT


CERTIFICATE No :SFC 35233700


Page 2 of 3

Description of Assessed Product and Performance (cont'd)

Pipe Type & Material	Nominal Pipe Diameter (mm)	Nominal Pipe Wall Thickness (mm)	Local Fire Stopping System	Refer Figure	FRL
uPVC pipe	32	1.9		Fig. 1	-/240/240
	40	2.0			-/240/240
	50	2.2			-/240/240
	65	2.7			-/240/240
uPVC pipe with	32	1.9		Fig. 2	-/240/240
Flange of elbow	40	2.0			-/240/240
fitted into collar, DWV Bend × 88°	50	2.2			-/240/240
	65	2.7			-/240/240
PP pipe	32	2.9	Hilti CP 680 75/2.5" N	Fig. 1	-/240/240
	40	3.7			-/240/240
	50	4.6			-/240/240
	63	5.8			-/240/240
	75	6.8			-/240/240
	32	4.4			-/240/240
	40	5.5			-/240/240
PP-R pipe	50	6.9			-/240/240
	63	8.6			-/240/240
	75	10.3			-/240/240
Silere pipe	58	4.2			-/240/240
	32	2.9-3.3			-/240/240
-	40	3.7-4.2			-/240/240
PE pipe	50	4.6-5.2			-/240/240
-	63	5.8-6.5			-/240/240
	75	6.8-7.6			-/240/240
HDPE	50	3.0			-/240/240
	56	56 3.0		-/240/240	
	63	3.0			-/240/240
	75	3.0			-/240/240







Optional Ultrafloor formwork with a hole cut to completely expose the metal ring part of the collar



Refer to the referenced assessment reports for a complete description of the assessed construction.

DWV Bend × 88°

